

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NENW

Location ID: 334775

Date: 10/15/2024



Oct 15, 2024 at 11:18:22
1845 County Road 309
Parachute CO 81635
United States



Oct 15, 2024 at 11:19:02
1845 County Road 309
Parachute CO 81635
United States

Location Entrance – Photo #04221

Wellheads – Photo #04222

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NENW

Location ID: 334775

Date: 10/15/2024



Separators – Photo #04224



Tank Battery – Photo #04223

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NENW

Location ID: 334775

Date: 10/15/2024



Insufficient Erosion Control – Photo #04234



Insufficient Erosion Control/Sediment Transport from Lease Road – Photo #04236

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NENW

Location ID: 334775

Date: 10/15/2024



Insufficient Erosion Control/Sediment Transport from Lease Road – Photo #04237



Insufficient Erosion Control/Sediment Transport from Lease Road – Photo #04238