

Inspection Photos

October 8th, 2024

Operator: Willford Resources - 96735

Location ID: 325461

Inspection Document #: 714001345

La Plata County, CO

Township: NENW 12 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ted 1
Location ID: 325461

10/8/24
+37.126113,-108.103761
187° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area from the northern edge facing center.

API #: 067-06410

Inspection Photos
Location Name: Ted 1
Location ID: 325461




Photo 2. Cardinal photos taken from the center of the disturbance, left photo facing north, right photo facing east.

Inspection Photos
Location Name: Ted 1
Location ID: 325461



Photo 3. Cardinal photos taken from the center of the disturbance, left photo facing south, right photo facing west. Note: Reclaimed area vegetation appears consistent with adjacent reference area (see photo 4).

Inspection Photos
Location Name: Ted 1
Location ID: 325461



10/8/24
+37.124155,-108.103527
240° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area composed of Smooth Brome, Crested Wheatgrass and Field Bindweed.

API #: 067-06410