

# Inspection Photos

October 8th, 2024

Operator: Willford Resources - 96735

Location ID: 325495

Inspection Document #: 714001346

La Plata County, CO

Township: SENW 12 33N 12W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**


Department of Natural Resources

Inspection Photos  
Location Name: Henderson 1  
Location ID: 325495



**Photo 1.** View of the project area from the northern edge facing center.

Inspection Photos  
Location Name: Henderson 1  
Location ID: 325495



**Photo 2.** Cardinal photos taken from the center of the disturbance, left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Henderson 1  
Location ID: 325495



**Photo 3.** Cardinal photos taken from the center of the disturbance, left photo facing south, right photo facing west. Note: Area is dominated by weedy annual vegetation including but not limited to Field Bindweed, Russian Thistle and Pepperweed.

Inspection Photos  
Location Name: Henderson 1  
Location ID: 325495



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area comprised predominantly of Field Bindweed and Rubber Rabbitbrush.

API #: 067-06492