

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403964320

Receive Date:  
\_\_\_\_\_

Report taken by:  
\_\_\_\_\_

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	<b>Phone Numbers</b>
Address: 1099 18TH STREET SUITE 1500		Phone: (970) 730-7281
City: DENVER State: CO Zip: 80202		Mobile: ( )
Contact Person: Dan Peterson	Email: danpeterson@chevron.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 27437 Initial Form 27 Document #: 403294209

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

SITE INFORMATION

Yes Multiple Facilities

Facility Type: LOCATION	Facility ID: 329441	API #: _____	County Name: WELD
Facility Name: BERNHARDT-64N67W 13NWNE	Latitude: 40.316842	Longitude: -104.836827	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NWNE	Sec: 13	Twp: 4N	Range: 67W Meridian: 6 Sensitive Area? Yes

Facility Type: LOCATION	Facility ID: 332683	API #: _____	County Name: WELD
Facility Name: BERNHARDT O-64N67W 13SWNE	Latitude: 40.313270	Longitude: -104.836920	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SWNE	Sec: 13	Twp: 4N	Range: 67W Meridian: 6 Sensitive Area? Yes

Facility Type: SPILL OR RELEASE      Facility ID: 484712      API #: \_\_\_\_\_      County Name: WELD  
 Facility Name: BERNHARDT-64N67W 13NWNE      Latitude: 40.318437      Longitude: -104.839044  
 \*\* correct Lat/Long if needed: Latitude: \_\_\_\_\_      Longitude: \_\_\_\_\_  
 QtrQtr: NWNE      Sec: 13      Twp: 4N      Range: 67W      Meridian: 6      Sensitive Area? Yes

**SITE CONDITIONS**

General soil type - USCS Classifications SW      Most Sensitive Adjacent Land Use Cropland  
 Is domestic water well within 1/4 mile? Yes      Is surface water within 1/4 mile? No  
 Is groundwater less than 20 feet below ground surface? No

**Other Potential Receptors within 1/4 mile**

Mule Deer Severe Winter Range  
 Railroad 80ft NE  
 Farm Structures 0.16/0.19 WNW  
 Residential 0.24 SW, 0.23 WSW, 0.12 W, 0.11 WNW, 0.11 NW, 0.13 N, 0.09 NE

# SITE INVESTIGATION PLAN

## **TYPE OF WASTE:**

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input checked="" type="checkbox"/> Oil            | <input type="checkbox"/> Tank Bottoms                |  |
| <input type="checkbox"/> Condensate                | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## **DESCRIPTION OF IMPACT**

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab analysis if encountered
UNDETERMINED	SOILS	NA	Lab analysis

## **INITIAL ACTION SUMMARY**

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A site investigation will be conducted pursuant to COGCC Rule 911 at the BERNHARDT 13-12 and BERNHARDT O13-07 Tank Battery locations.

## **PROPOSED SAMPLING PLAN**

### **Proposed Soil Sampling**

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Grab confirmation soil samples were collected from the produced water vessel(s) excavation, beneath the ground oil tank(s), and at the separator(s). Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, and boron. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

### **Proposed Groundwater Sampling**

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Groundwater was not encountered during the site investigation.

### **Proposed Surface Water Sampling**

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

## **Additional Investigative Actions**

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Visual inspection at the tank battery area occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. The ECMC Tank Battery and Produced Water Vessel Closure Checklists were utilized and filled out during the abandonment process. A photolog is attached.

# SITE INVESTIGATION REPORT

## **SAMPLE SUMMARY**

<b>Soil</b>	<b>NA / ND</b>
Number of soil samples collected <u>        6        </u>	-- Highest concentration of TPH (mg/kg) <u>        57        </u>

Number of soil samples exceeding 915-1 3 -- Highest concentration of SAR 0.947  
 Was the areal and vertical extent of soil contamination delineated? No BTEX > 915-1 Yes  
 Approximate areal extent (square feet) 300 Vertical Extent > 915-1 (in feet) 4

**Groundwater**

Number of groundwater samples collected 0 Highest concentration of Benzene (µg/l) \_\_\_\_\_  
 Was extent of groundwater contaminated delineated? No Highest concentration of Toluene (µg/l) \_\_\_\_\_  
 Depth to groundwater (below ground surface, in feet) \_\_\_\_\_ Highest concentration of Ethylbenzene (µg/l) \_\_\_\_\_  
 Number of groundwater monitoring wells installed \_\_\_\_\_ Highest concentration of Xylene (µg/l) \_\_\_\_\_  
 Number of groundwater samples exceeding 915-1 \_\_\_\_\_ Highest concentration of Methane (mg/l) \_\_\_\_\_

**Surface Water**

0 Number of surface water samples collected  
 \_\_\_\_\_ Number of surface water samples exceeding 915-1  
 If surface water is impacted, other agency notification may be required.

**OTHER INVESTIGATION INFORMATION**

Were impacts to adjacent property or offsite impacts identified?  
 \_\_\_\_\_

Were background samples collected as part of this site investigation?  
 \_\_\_\_\_

Was investigation derived waste (IDW) generated as part of this investigation?  
 Volume of solid waste (cubic yards) \_\_\_\_\_ Volume of liquid waste (barrels) \_\_\_\_\_

Is further site investigation required?  
 \_\_\_\_\_

**REMEDIAL ACTION PLAN**

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? Yes

**SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

Impacted soil was removed from the release area at the Bernhardt former tank battery location by excavation. The impacted soil was disposed of at an approved landfill as non-hazardous waste in accordance with Rules 905 and 906. Copies of the waste manifests are available upon request.

**REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Excavation of impacted soil was undertaken to remove impacts observed at two feet bgs in the PWV01 N Wall sample location and at four feet bgs in the SEP02 and PWV02 sample locations. Confirmation soil samples were collected and analyzed for ECOM Table 915 organic and Soil Suitability for Reclamation constituents (TPH, BTEX, 1,2,4 Trimethylbenzene, 1,3,5 Trimethylbenzene, Naphthalene, Polycyclic Aromatic Hydrocarbons [PAHs], pH, SAR, EC, and Boron) and ECOM Table 915-1 metals. Groundwater was not encountered.

Elevated concentrations of pH, barium and arsenic are proposed to be attributed to native soil conditions, based on concentrations observed in local background samples collected adjacent to the site's excavations. Sample locations, located within the PWV02 excavation, exhibiting concentrations of chromium not attributable to background concentrations, and greater than the Table 915-1 PGSSLs and RSSLs will be resampled to verify the presence of elevated concentrations of chromium (VI) initially observed. Remedial alternatives will be evaluated if concentrations of elevated chromium (VI) are confirmed following receipt of resampling results. A no further action designation will be requested if chromium concentrations comply with the Table 915-1 standard or are attributable to background concentrations.

**Soil Remediation Summary**

In Situ  Ex Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

Yes \_\_\_\_\_ Excavate and offsite disposal  
If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_ 112  
Name of Licensed Disposal Facility or ECMC Facility ID # \_\_\_\_\_  
\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

**Groundwater Remediation Summary**

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

**GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

NA

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

### Approved Reporting Schedule:

Quarterly     Semi-Annually     Annually     Other

### Request Alternative Reporting Schedule:

Semi-Annually     Annually     Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:     Groundwater Monitoring     Land Treatment Progress Report     O&M Report

Other Supplemental Form 27

## Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with COGCC rules. Records are available on the COGCC's website.

Operator anticipates the remaining cost for this project to be: \$ 0

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

No beneficial use

Volume of E&P Waste (solid) in cubic yards 112

E&P waste (solid) description Hydrocarbon impacted soil

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: Buffalo Ridge Landfill in Keenesburg, Colorado

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with COGCC 1000 Series Rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim  Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. \_\_\_\_\_

Proposed date of completion of Reclamation. \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 12/15/2022

Actual Spill or Release date, or date of discovery. 05/25/2023

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 05/15/2023

Proposed site investigation commencement. 02/01/2023

Proposed completion of site investigation. 05/15/2023

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 05/15/2023

Proposed date of completion of Remediation. 02/15/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

Additional sampling is needed to confirm or deny the presence of elevated chromium (VI) in the PWV02 excavation.

**OPERATOR COMMENT**

This form serves to comply with the Rule 913.e. reporting schedule. Pending ECMC approval, location, landowner approval, and crew availability, the Operator will complete the additional site investigation as outlined in this proposed Site Investigation Report workplan prior to the Proposed completion of remediation date detailed in the Implementation schedule. Supplemental Form 27s will be prepared and submitted on a quarterly schedule to provide updates and progress of the remediation until closure criteria has been achieved.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Ethan Black

Title: Consultant

Submit Date: \_\_\_\_\_

Email: ethanb@fremontenv.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: 27437

**COA Type**

**Description**

0 COA	

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num**

**Name**

403964351	OTHER
-----------	-------

Total Attach: 1 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)