

Inspection Photos
Location Name: NEWLANDER-1
Location ID: 320142



Photo #1 Crude tank.



Photo #2 P/W tank.

Inspection Photos
Location Name: NEWLANDER-1
Location ID: 320142



Photo #3 Separator and meter run.



Photo #4 Pump Jack.