

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 10/22/2024



East End of Location – Photo #04326



Wellheads – Photo #04328



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 10/22/2024



Separators – Photo #04329



Tank Battery – Photo #04342

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 10/22/2024



Unsecured Separator – Photo #04330



Unsecured Separator – Photo #04334



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 10/22/2024



Unsecured Separator – Photo #04332



Open-Ended Line – Photo #04333

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 10/22/2024



Stored Supplies – Photo #04335



Stored Supplies – Photo #04337



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 10-23

Location ID: 323787

Date: 10/22/2024



**Lack of Stabilization – Photo #04339**



**Insufficient Tracking BMPs – Photo #04340**