

Inspection Photos

Location Name: DF Ranch 02-31, 33 Tank Battery

Location ID: 461586



Photo 1 – Heater Treaters and ECD



Photo 2 – Unused Secondary East of Treater Housing

Inspection Photos

Location Name: DF Ranch 02-31, 33 Tank Battery

Location ID: 461586



Photo 3 – Tank Battery



Photo 4 – New Operator Label needs installed

Inspection Photos
Location Name: DF Ranch 02-31, 33 Tank Battery
Location ID: 461586



Photo 5 – Tank Battery Sign




Photo 6 – Tank Battery