

Inspection Photos


Location: SG INTERESTS I LTD FEDERAL-610S91W/25SESE

Location ID: 324478

Date: 10/21/2024



Oct 21, 2024 at 1:16:47 PM
+39.155865,-107.495440 ±4.72m



Oct 21, 2024 at 1:29:17 PM
+39.155948,-107.495727 ±4.71m

Photo # 7697 Entrance to location

Photo # 7715 Location

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/25SESE

Location ID: 324478

Date: 10/21/2024



Photo # 7698 Location



Photo # 7707 Location

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/25SESE

Location ID: 324478

Date: 10/21/2024



Photo # 7714 Location



Photo # 7727 SW corner of location

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/25SESE

Location ID: 324478

Date: 10/21/2024



Photo # 7728 SE corner of location



Photo # 7731 NW corner of location

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/25SESE

Location ID: 324478

Date: 10/21/2024



Photo # 7732 NE corner of location



Photo # 7722 Tank heater open to wildlife hazard/ available for entry by wildlife

Inspection Photos

Location: SG INTERESTS I LTD FEDERAL-610S91W/25SESE

Location ID: 324478

Date: 10/21/2024



Photo # 7723 Tank heater open to wildlife hazard/ available for entry by wildlife

