

# Final Reclamation Inspection

October 17, 2024

Operator: MAGPIE OPERATING INC - 52530

Location ID: 307131

Inspection Document #: 697505537

Larimer County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



**Photo 1.** Photo taken from the entrance of location, facing West. Photo illustrates the field has been recently harvested. Even though the field was harvested, Staff was able to assess vegetative establishment and compare that to reference crop areas.



Inspection Photos  
Location Name: SAULCY #3  
Location ID: 307131



**Photo 2.** Photo taken from a portion of the location access road, facing North. Photo illustrates the access road crop growth is reflective of reference crop areas.



**Photo 3.** Photo taken from the location, facing South. See comments under Photo 2.



Inspection Photos  
Location Name: SAULCY #3  
Location ID: 307131



**Photo 4.** Photo taken from the location, facing West. See comments under Photo 2.



**Photo 5.** Photo taken from the location, facing North. See comments under Photo 2.





**Photo 6.** Photo taken from the location, facing East. See comments under Photo 2.