

Inspection Photos

API: 017-07388

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 10/21/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the access road which has not been recontoured and reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321902 | Date: 10/21/2024

Inspection Photos



Photo 2. Facing southeast toward the location which has not been reclaimed.



Inspection Photos



Photo 3. Facing southeast at the location. This bare area is approximately 125 ft. by 15ft.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321902 | Date: 10/21/2024

Inspection Photos



Photo 4. South side of the location facing northwest.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321902 | Date: 10/21/2024

Inspection Photos



Photo 5. West side of the location facing east. There are areas of bare soil and undesirable weeds.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321902 | Date: 10/21/2024