

# Inspection Photos

ID:412172

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 10/21/2024

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the SPEAKER UNIT COMPRESSOR and tank battery.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID:412172 | Date: 10/21/2024

Inspection Photos



Photo 2. Facing toward the tank battery.



## Inspection Photos



**Photo 3.** There are oil stained soils at the base of these tanks that need to be cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID:412172 | Date: 10/21/2024

## Inspection Photos



**Photo 4.** East side of the location facing west on top of the topsoil pile. There are undesirable weeds throughout this area.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID:412172 | Date: 10/21/2024

## Inspection Photos



**Photo 5.** Facing southwest toward the interim reclamation area. This entire area at the east side of the location consists of undesirable weeds that must be controlled. This area will need to be reseeded to establish perennial vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID:412172 | Date: 10/21/2024