

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: MCINTYRE CANYON #17-21

Location ID: 316818 API #: 05-113-06080

Inspection Date: 10/22/2024 Inspection Doc#: 693807846



Wellhead with fence and sign



Separator and Meter Housing

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: MCINTYRE CANYON #17-21

Location ID: 316818

API #: 05-113-06080

Inspection Date: 10/22/2024

Inspection Doc#: 693807846



Tank battery



Tank battery (Blowdown)

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: MCINTYRE CANYON #17-21

Location ID: 316818 API #: 05-113-06080

Inspection Date: 10/22/2024 Inspection Doc#: 693807846



Telemetry



Location overview looking E