

Final Reclamation and Stormwater Inspection

Date: 10/21/2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 414464

Inspection Document #: 708201720

Broomfield County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: BOA 12-23
Location ID: 414464



Photo 1. Facing north. Operator submitted Form 4 Sundry Notices stating the above wells were not drilled. The Form 2A (doc #400004078) expired on 11/12/2012. Location was not constructed at the proposed well locations based off field observations.

Inspection Photos
Location Name: BOA 12-23
Location ID: 414464



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: BOA 12-23
Location ID: 414464



Photo 3. Facing south; see comments in Photo 1.

Inspection Photos
Location Name: BOA 12-23
Location ID: 414464



Photo 4. Facing west; see comments in Photo 1.