

# Final Reclamation and Stormwater Inspection

Date: 10/21/2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP-  
47120

Location ID: 414493

Inspection Document #: 708201723

Broomfield County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Bury 4-23  
Location ID: 414493



**Photo 1.** Operator submitted a Form 4 Sundry Notice (doc #2332123) stating the above well was not drilled. The Form 2A (doc #400004126) expired on 11/17/2012. Location was not constructed at the proposed well location based off field observations.