

Inspection Photos

October 22nd, 2024

Operator: Arkoma Operations - 10766

Location ID: 311895

Inspection Document #: 714001379

La Plata County, CO

Township: NWSW 15 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Terrell/IGW
Location ID: 311895



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Terrell/IGW
Location ID: 311895

10/22/24
313° NW



Photo 2. Large patch of Canada Thistle observed in the northeast corner of the active pad.

Inspection Photos
Location Name: Terrell/IGW
Location ID: 311895

10/22/24
242° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of the western interim reclamation area composed of predominantly of Smooth Brome and Western Wheatgrass.

API #: Multi Well Pad

Inspection Photos
Location Name: Terrell/IGW
Location ID: 311895



Photo 4. View of active erosion and sediment transport/deposition occurring in the SW corner of the location on the cut slope.



Photo 5. View of perimeter wattles that are damaged and no longer functioning, maintenance is needed in this area.

Inspection Photos
Location Name: Terrell/IGW
Location ID: 311895



Photo 6. Reference area composed of Indian Ricegrass and Juniper.