

Inspection Photos
Location Name: George H Gerhardt 4
Location ID: 326734



Photo 1 Location.



Photo 2 Well site.

Inspection Photos
Location Name: George H Gerhardt 4
Location ID: 326734



Photo 3 Wellhead.



Photo 4 Wellhead sign Peeling and need to be replaced.

Inspection Photos
Location Name: George H Gerhardt 4
Location ID: 326734



Photo 5 Unnecessary equip. in the dead vegetation.



Photo 6 Unnecessary equip. in the dead vegetation.

Inspection Photos
Location Name: George H Gerhardt 4
Location ID: 326734



Photo 7 Unnecessary equip.