

Inspection Photos

API: 071-07927

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/23/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the reclaimed location. Perennial vegetation is establishing well throughout the location.



Inspection Photos



Photo 2. Facing northwest toward the reclaimed location. Perennial vegetation is establishing well throughout the location.



Inspection Photos



Photo 3. Facing south at the center of the location. This area has less vegetation establishment but appears stabilized.



Inspection Photos



Photo 4. Facing toward the west side of the location.



Inspection Photos



Photo 5. Facing southeast at the location..



Inspection Photos



Photo 6. This run-on ditch from the road needs additional seeding and the check dams needs to be cleaned out.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-07927 | Date: 10/23/2024