

# Inspection Photos

API: 071-06716

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 10/23/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest toward the reclaimed road. The vegetation is not progressing in areas of the road and additional seeding will need to be performed.





## Inspection Photos



**Photo 2.** Drone aerial photo facing down along the access road. Additional seeding will need to be performed.





## Inspection Photos



**Photo 3.** Drone aerial photo facing southwest.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** Further along the reclaimed road are areas of erosion which will need some repairs and reseeding..





## Inspection Photos



**Photo 5.** Facing northeast at the top of the ridge. The perennial vegetation is progressing well to the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 6.** Facing north at the slope of the location.





## Inspection Photos



**Photo 7.** Facing northeast at the location. There are areas that could benefit from additional seeding.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 8.** Facing northwest at the location. There are areas that could benefit from additional seeding.

