

Inspection Photos

API: 071-06634

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/23/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. There is a unused cattle guard that will need to be removed. Located on the ridge just south of the wellsite.



Inspection Photos



Photo 2. Facing northwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-06634 | Date: 10/23/2024

Inspection Photos



Photo 3. Facing northeast toward the fill slope.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-06634 | Date: 10/23/2024