

SLANOVICH #32-1  
LOCATION ID 322227  
PHOTOLOG

DRILL CUTTINGS REMOVED



hauling off cuttings

October 17, 2024 11:28 AM

DRILL CUTTINGS REMOVED



hauling off cuttings

October 17, 2024 11:28 AM

DRILL CUTTINGS REMOVED



stained soil removed

October 18, 2024 10:20 AM

Tank Battery – Tank has been removed and leak has been cleaned



Tank Battery – Tank has been removed and leak has been cleaned



Slanovich 32-1

Collection of Drill Cuttings for Disposal being picked up by Twin Enviro Services on 9/16/2024.



### Slanovich 32-1


Dripping Leak Repairs, identified at the backside of the tank valve. Soil cleanup is clearly seen just below valve where the impacted soil was removed.



Tank Battery – Tank has been removed and leak has been cleaned



Access Road and Berms



Reclaimed areas to control erosion



Reclaimed areas

