

# Inspection Photos

Location Name: TEP Rocky Mountain LLC TRANT Pad

Location # 335081



Photo # 7390 From entrance to location



Photo # 7391 Location

# Inspection Photos

Location Name: TEP Rocky Mountain LLC TRANT Pad

Location # 335081



Photo # 7392 Location



Photo # 7393 Location

# Inspection Photos

Location Name: TEP Rocky Mountain LLC TRANT Pad  
Location # 335081



Photo # 7394 Location

Photo # 7395 Location

**Inspection Photos**  
**Location Name: TEP Rocky Mountain LLC TRANT Pad**  
**Location # 335081**



**Photo # 7396 Location**

**Photo # 7397 Location**

## Inspection Photos

Location Name: TEP Rocky Mountain LLC TRANT Pad

Location # 335081



Photo # 7398 Sign weathered/faded & starting to become illegible



Photo # 7399 Sign weathered/faded & starting to become illegible

Inspection Photos  
Location Name: TEP Rocky Mountain LLC TRANT Pad  
Location # 335081



Photo # 7400 Some required info on tank label is weathered & illegible