

Inspection Photos
Location Name: Wild Horse GV 28-72HN
Location ID: 431573



Photo 1 – EDI Compressor



Photo 2 – Inlets and Outlets LOTO

Inspection Photos
Location Name: Wild Horse GV 28-72HN
Location ID: 431573




Photo 3 – EDI Compressor



Photo 4 – Thermal Event at Exhaust

Inspection Photos
Location Name: Wild Horse GV 28-72HN
Location ID: 431573



Energy and Carbon Management Commission
40.71342, -104.20171, 4906.2ft
10/23/2024 14:17:25

Photo 5 – Tank Battery Sign