

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 10/24/2024



Location Entrance – Photo #04499



Location – Photo #04502

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 10/24/2024



Location – Photo #04500



Location – Photo #04501

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 10/24/2024



Rill Erosion/Sediment Transport Offsite – Photo #04497



Rill Erosion/Sediment Transport Offsite – Photo #04498