

## Inspection Photos

Location Name: LAWLEY-66N64W/4NWSE

Location ID: 332482



**Photo #1**

**Lawley 33-4 (123-22359) Wellsite**

**Plugged & Abandoned | PA**

*NOT cut/caped*



**Photo #2**

**Lawley 43-4, 44-4D, 33-4 Battery site**

**Inactive | Shut-down**

**Equipment Documented; Loc ID: 332483**

*Formerly served:*

*Lawley 43-4, 44-4D, 33-4; Plugged & Abandoned | PA*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: LAWLEY-66N64W/4NWSE

Location ID: 332482



**Photo #3**

**Lawley 43-4, 44-4D, 33-4 Battery site**

**Inactive | Shut-down**

*Well / Battery entrance*



**COLORADO**  
**Energy & Carbon Management**  
**Commission**

Department of Natural Resources