

Inspection Photos

API: 071-08322

Operator: OGRIS OPERATING LLC

Inspection Date: 10/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the location.



Inspection Photos



Photo 2. It appears the oil staining was cleaned up at the base of the pumpjack..

