

# Inspection Photos

API: 071-08651

Operator: OGRIS OPERATING LLC

Inspection Date: 10/28/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the location.



## Inspection Photos



**Photo 2.** There is more trash found along the east fill slope.




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-08651 | Date: 10/28/2024

## Inspection Photos



**Photo 3.** Facing toward the wellhead. There is stained soils at the hose outlet at red arrow.

