

Inspection Photos

API: 071-09632

Operator: OGRIS OPERATING LLC

Inspection Date: 10/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the location.



Inspection Photos



Photo 2. Facing southeast toward the well site.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-09632 | Date: 10/28/2024

Inspection Photos



Photo 3. There is still oil in the engine skid from the leaking engine and oil has spilled onto the ground.

