

Inspection Photos
Location Name: Drake Pad
Location ID: 454899



Lease road entrance sign



Energy & Carbon Management Commission
40.58793, -104.8371, 1532.4m, 189°
10/30/2024 12:31:47

Inspection Photos
Location Name: Drake Pad
Location ID: 454899




Uncovered cellar




Uncovered cellar

Inspection Photos
Location Name: Drake Pad
Location ID: 454899



Uncovered cellar



Uncovered cellar

Inspection Photos
Location Name: Drake Pad
Location ID: 454899



Uncovered cellar