

Inspection Photos

October 25th, 2024

Operator: Kinder Morgan - 46685

Location ID: 313504

Inspection Document #: 714001393

Montezuma County, CO

Township: SENW 20 37N 18W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McElmo Dome Unit 20-37-18 YC 2
Location ID: 313504

10/25/24
228° SW



Photo 1. View of the well pad taken from the access point facing center.



KINDER MORGAN
CO₂ COMPANY, LLC

McELMO DOME UNIT-YC-2
SEC. 20, T37N, R18W
2435' FNL & 1383' FWL
LEASE NO. C-11644
MONTEZUMA COUNTY, CO OR
EMERGENCY #970-882-5522 911

API #: 083-06374

Inspection Photos
Location Name: McElmo Dome Unit 20-37-18 YC 2
Location ID: 313504



Photo 2. Gap in cellar grate was not observed during this inspection. Wildlife BMPs appear to be in working condition.

Inspection Photos

Location Name: McElmo Dome Unit 20-37-18 YC 2

Location ID: 313504



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of western interim reclamation area/fill slope composed of predominantly Crested Wheatgrass and Rubber Rabbitbrush.

API #: 083-06374

Inspection Photos

Location Name: McElmo Dome Unit 20-37-18 YC 2

Location ID: 313504

10/25/24
264° W



Photo 4. Reference area composed of James Galleta, Crested Wheatgrass and Broom Snakeweed.