

Inspection Photos

October 25th, 2024

Operator: Kinder Morgan - 46685

Location ID: 313572

Inspection Document #: 714001396

Montezuma County, CO

Township: SWNE 10 37N 18W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: McElmo Dome 10-37-18 YE 2

Location ID: 313572

10/25/24
254° W



10/25/24
247° SW

Photo 1. View of the well disturbance taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 083-06577

Inspection Photos

Location Name: McElmo Dome 10-37-18 YE 2

Location ID: 313572

10/25/24
259° W



Photo 2. View of the northern interim reclamation area composed of Intermediate Wheatgrass, Rubber Rabbitbrush and Broom Snakeweed. No weeds observed.

Inspection Photos

Location Name: McElmo Dome 10-37-18 YE 2

Location ID: 313572

10/25/24
48° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Reference area composed of Juniper, Sagebrush, Blue Grama and Antelope Bitterbrush.

API #: 083-06577