

Inspection Photos

October 28th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 325300

Inspection Document #: 714001403

La Plata County, CO

Township: NENE 1 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Squires 1, 4
Location ID: 325300



10/28/24
120° SE



10/28/24
122° SE



10/28/24
141° SE

Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Squires 1, 4
Location ID: 325300



Photo 2. View of erosion issues in the southern portion of the disturbance that remain unresolved.

Inspection Photos
Location Name: Squires 1, 4
Location ID: 325300

10/28/24
69° E



Photo 3. View of eastern cut slope that remains un vegetated and with bare soils.

Inspection Photos
Location Name: Squires 1, 4
Location ID: 325300

10/28/24
278° W



Photo 4. View of active pasture reference area.

