

Inspection Photos  
Location Name: Musick-McClintock #3  
Location ID: 311325



Photo 1: No sign displayed

Photo 2: No contents or capacity

**Inspection Photos**  
**Location Name: Musick-McClintock #3**  
**Location ID: 311325**



**Photo 3: Overgrown vegetation**

**Photo 4: Overgrown vegetation**

**Inspection Photos**  
**Location Name: Musick-McClintock #3**  
**Location ID: 311325**



**Photo 5: Overgrown vegetation(facing south)**

**Photo 6: Overgrown vegetation (facing West)**

**Inspection Photos**  
**Location Name: Musick-McClintock #3**  
**Location ID: 311325**



**Photo 7: Overgrown vegetation (facing NE)**

**Photo 8: Overgrown vegetation (facing NW)**