

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 1: Tank Battery Sign (faded)

Photo 2: Overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 3: Overgrown vegetation, no contents/capacity displayed

Photo 4: Overgrown vegetation, stained soil

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 5: Stained soil

Photo 6: Overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 7: Overgrown vegetation

Photo 8: Overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 9: Overgrown vegetation

Photo 10: Overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 11: Overgrown vegetation, No Sign

Photo 12: Overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 13: Overgrown vegetation