

**Inspection Photos**  
**Location Name: Musick-McClintock #2**  
**Location ID: 318633**



**Photo 1: Overgrown vegetation removed from access road**

**Photo 2: Wellhead Sign**

**Inspection Photos**  
**Location Name: Musick-McClintock #2**  
**Location ID: 318633**



**Photo 3: Overgrown vegetation**

**Photo 4: Overgrown vegetation**

Inspection Photos  
Location Name: Musick-McClintock #2  
Location ID: 318633



Photo 5: Overgrown vegetation

Photo 6: Overgrown vegetation, fencing in disrepair

**Inspection Photos**  
**Location Name: Musick-McClintock #2**  
**Location ID: 318633**



**Photo 7: Overgrown vegetation**