

Final Reclamation and Stormwater Inspection

Date: 10/25/2024

Operator: BONANZA CREEK ENERGY OPERATING
COMPANY - 8960

Location ID: 305849

Inspection Document #: 708201749

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pronghorn 14- 8
Location ID: 305849



Photo 1. Taken from the production areas facing southwest along the access road. Red line illustrates that portions of the former access road do not appear to have been recontoured.

Inspection Photos
Location Name: Pronghorn 14- 8
Location ID: 305849



Photo 2. Facing south along the access road. Red line illustrates that portions of the former access road do not appear to have been recontoured.

Inspection Photos
Location Name: Pronghorn 14- 8
Location ID: 305849



Photo 3. Taken near the center of the location, facing west. Red outlined portion does not appear to have been recontoured.

Inspection Photos
Location Name: Pronghorn 14- 8
Location ID: 305849



Photo 4. Continue from Photo 3, facing south. See comments in Photo 3.

Inspection Photos
Location Name: Pronghorn 14- 8
Location ID: 305849



Photo 5. Taken near the center of the location, facing north. The former location appears to be graded flat and has not been contoured to match the surrounding topography.

Inspection Photos
Location Name: Pronghorn 14- 8
Location ID: 305849



Photo 6. Taken near the former separator location, facing east. The former location is appears to be graded flat and has not been contoured to match the surrounding topography.

Inspection Photos
Location Name: Pronghorn 14- 8
Location ID: 305849



Photo 7. Non-uniform vegetation cover near the former separator.

Inspection Photos
Location Name: Pronghorn 14- 8
Location ID: 305849



Photo 8. Non-uniform vegetation near the former tank battery.