

Inspection Photos

Location Name: CAERUS PICEANCE LLC, ENCANA-67S95W/21NWNW

Location ID: 335047

Date: 10/30/2024



Location Entrance – Photo #04582



Location – Photo #04584

Inspection Photos

Location Name: CAERUS PICEANCE LLC, ENCANA-67S95W/21NWNW

Location ID: 335047

Date: 10/30/2024



Location – Photo #04587



Location – Photo #04585



Inspection Photos

Location Name: CAERUS PICEANCE LLC, ENCANA-67S95W/21NWNW

Location ID: 335047

Date: 10/30/2024



Location – Photo #04586



Lack of Stabilization/Standing Water – Photo #04583