

Inspection Photos

October 28th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333627

Inspection Document #: 714001415

La Plata County, CO

Township: SWNE 3 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Schofield A1
Location ID: 333627



10/28/24
30° NE



10/28/24
18° N

Photo 1. View of the well disturbance taken from the access point facing center. Note location is shared with the Logos Operating Colorado 32-7 11 well. Note: location sign is bent but still legible.

Inspection Photos
Location Name: Schofield A1
Location ID: 333627



Photo 2. View of impacted surface material observed at the lube tank/pump jack muffler tube.

Inspection Photos
Location Name: Schofield A1
Location ID: 333627



Photo 3. View of erosion and storm water BMPs that are no longer functioning in the eastern interim reclamation area.

Inspection Photos
Location Name: Schofield A1
Location ID: 333627



Inspection Photos
Location Name: Schofield A1
Location ID: 333627

