

Inspection Photos

October 28th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325823

Inspection Document #: 714001416

La Plata County, CO

Township: NWSE 34 33N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Spanish Fork B1
Location ID: 325823



Photo 1. View of the well disturbance taken from the access point facing center.



API #: 067-07037

Inspection Photos
Location Name: Spanish Fork B1
Location ID: 325823



10/28/24
250° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the western interim reclamation area composed of Intermediate Wheatgrass and Blue Grama.

API #: 067-07037

Inspection Photos
Location Name: Spanish Fork B1
Location ID: 325823



Photo 3. Small spill observed on pump jack pad at muffler.



Inspection Photos
Location Name: Spanish Fork B1
Location ID: 325823



Photo 4. Weedy kochia debris observed lining the edge of the active pad.

Inspection Photos
Location Name: Spanish Fork B1
Location ID: 325823



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Juniper, Sagebrush and Blue Grama.

API #: 067-07037