

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH-67S96W/26SWSE

Location ID: 334405

Date: 10/31/2024



Location Entrance – Photo #04597



Location – Photo #04604



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH-67S96W/26SWSE

Location ID: 334405

Date: 10/31/2024



Oct 31, 2024 at 11:37:25  
1691 County Road 300  
Parachute CO 81635  
United States

Location – Photo #04600



Oct 31, 2024 at 11:38:36  
1691 County Road 300  
Parachute CO 81635  
United States

Location – Photo #04603

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH-67S96W/26SWSE

Location ID: 334405

Date: 10/31/2024



**Nitrogen Leak – Photo #04599**



**Wildlife Entry Hazards – Photo #04601**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH-67S96W/26SWSE

Location ID: 334405

Date: 10/31/2024



Wildlife Entry Hazards – Photo #04602



Lack of Stabilization on Access Road – Photo #04605

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH-67S96W/26SWSE

Location ID: 334405

Date: 10/31/2024



Insufficient Tracking BMPs – Photo #04606