



Remediation Soil & Groundwater Sampling Fieldsheet

* * * Facility Information * * *

O&G Site Name	Burchfield 30-21 AD Kurtz Facility	Client	OXY	REM Project #	32537
Weather	Sunny 85	Surface Flow Direction	Flat		
API/TB#	319489	Liner present?	Yes	Site Coordinates	40.216428, -104.899076

Directions to Well: CR 34 & 17, E. 6/10, SW. 1.2 Miles, W. 2/10 into On loc: Burchfield 30-21, Albert D Kurtz GU C True 1

* * * Sampling Information * * *

Sample Date	09/18/24
Sampler(s)	JC, SE

Sample ID	Time	Date	Lab?	PID (ppm)	Location Description	Staining/ Odor	Color/ Lithology
AST01-B01@3"	1400	9/18/24	Y	1.1	SE AST bottom	None	red/brown silty sand
AST02-B01@3"	1405	9/18/24	Y	1.2	NE AST bottom	None	red/brown silty sand w/ gravel
AST03-B01@3"	1410	9/18/24	Y	1.3	NW AST bottom	None	red/brown silty sand w/ gravel
PW-B01@3'	1355	9/18/24	Y	0.7	PW bottom	None	brown silty sand
PW-N01@2'	1415	9/18/24	N	0.9	PW north side	None	brown silty sand
PW-S01@2'	1420	9/18/24	N	0.7	PW south side	None	brown silty sand
PW-E01@2'	1425	9/18/24	N	0.8	PW east side	None	brown silty sand
PW-W01@2'	1430	9/18/24	Y	1	PW west side	None	brown silty sand
AST01-B02@3"	1435	9/18/24	N	0.3	SE AST DL	None	brown silty sand
AST02-B02@3"	1440	9/18/24	N	1.5	NE AST DL	None	brown silty sand
AST03-B02@3"	1445	9/18/24	N	1.2	NW AST DL	None	brown silty sand w/ gravel
MH-B01@3"	1450	9/18/24	N	0.4	Meter House Bottom	None	brown silty sand w/ gravel
ECD-B01@3"	1455	9/18/24	N	1.1	ECD Bottom	None	brown silty sand w/ gravel
SEP-B01@4'	1500	9/18/24	Y	1.3	FL SEP Riser	None	brown sandy clay
SEP-B02@3'	1505	9/18/24	Y	1.4	DL SEP Riser	None	brown silty sand
DL-B01@5'	1510	9/18/24	N	14.7	Dump Line Bottom	None	dark brown silty sand w/ gravel
BG01@3"	1520	9/18/24	Y	0.7	East of Fac	None	light brown sand w/ gravel
BG01@2'	1525	9/18/24	Y	0.4	East of Fac	None	brown silty clay
BG01@4'	1530	9/18/24	Y	0.4	East of Fac	None	brown silty clay
BG02@3"	1535	9/18/24	Y	0.2	West of Fac	None	light brown silty sand
BG02@2'	1540	9/18/24	Y	0.6	West of Fac	None	brown sand
BG02@4'	1545	9/18/24	Y	0.6	West of Fac	None	brown sand

Decon Methods: Alconox & DI Water Depth GW observed: None

Soil Removal			Water Removal		GW Sampling				
Date	# of loads	CY	Date	BBLs	Sample ID	Date	Time	Odor?	Sheen?

Site Comments: Verification samples to be collected 9/19/24 for above liner samples.

Total :	Total :
Facility:	Facility:




Soil Sampling Photographic Log

Burchfield 30-21 AD Kurtz Facility

Remediation Project #: 32537

(September 18, 2024)

09/18/2024 14:18
+40.216405,-104.899042
Burchfield 30-21 AD Kurtz O SA Facility



Description:
AST01-B01 @ 3"
AST01-B02 @ 3"
Soil sample
location

09/18/2024 14:18
+40.216405,-104.899042
Burchfield 30-21 AD Kurtz O SA Facility



Description:
AST02-B01 @ 3"
AST02-B02 @ 3"

Soil sample
location

09/18/2024 14:18
+40.216405,-104.899042
Burchfield 30-21 AD Kurtz O SA Facility



Description:
AST03-B01 @ 3"
AST03-B02 @ 3"

Soil sample
location

09/18/2024 14:19
+40.216447,-104.899154
Burchfield 30-21 AD Kurtz O SA Facility



Description:
PW-B01 @ 3'
PW-E01 @ 2'
PW-S01 @ 2'

Soil sample
location

09/18/2024 14:18
+40.216405,-104.899042
Burchfield 30-21 AD Kurtz O SA Facility



Description:
PW-W01 @ 2'
PW-N01 @ 2'
Soil sample
location



Description:
DL-B01@5'

Soil sample
location

09/18/2024 14:25
+40.216216,-104.899513
Burchfield 30-21 AD Kurtz O SA Facility




Description:
ECD-B01@3"

Soil sample
location



Description:
MH-B01@3"

Soil sample
location



Description:
BG01 @ 3", 2', 4'

Background Soil
sample location



09/18/2024 15:35
+40.216225,-104.899577
Burchfield 30-21 AD Kurtz O SA Facility
BG02

Description:
BG02 @ 3", 2', 4'
Background Soil
sample location

09/18/2024 14:48
+40.216137,-104.899012
Burchfield 30-21 AD Kurtz O SA Facility
AST02



Description:
AST02
Tank Bottom



Soil Sampling Photographic Log

Burchfield 30-21 AD Kurtz O SA Facility

Remediation Project #: 32537
(September 19, 2024)



Description:

AST01-B01 @ 3" V

Soil sample location



09/19/2024 08:52
+40.216449,-104.899063
Burchfield 30-21 AD Kurtz O SA Facility

Description:
AST02-B01 @ 3" V
Soil sample location

09/19/2024 08:52
+40.216449,-104.899063
Burchfield 30-21 AD Kurtz O SA Facility



Description:
AST03-B01 @ 3" V
Soil sample location



Description:

PW-B01 @ 3' V
PW-W01 @ 2' V

Soil sample
location

09/19/2024 09:06
+40.216351,-104.899433
Burchfield 30-21 AD Kurtz O SA Facility



Description:

SEP-B01 @ 4'
SEP-B01 @ 4' V

**Soil sample
location**



Description:

**SEP-B02 @ 3'
SEP-B02 @ 3' V**

**Soil sample
location**



Description:

**AST01
Tank Bottom**



Description:

**AST03
Tank Bottom**