

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/19SWSW

Location ID: 335005

Date: 10/31/2024



Location Entrance/Standing Water – Photo #04621



Location – Photo #04626

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/19SWSW

Location ID: 335005

Date: 10/31/2024



Oct 31, 2024 at 12:17:59  
Parachute CO 81635  
United States

Location – Photo #04625



Oct 31, 2024 at 12:17:18  
Daybreak Rd  
Parachute CO 81635  
United States

Location – Photo #04623



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/19SWSW

Location ID: 335005

Date: 10/31/2024



Location – Photo #04622



Standing Water/Degradation on Access Road – Photo #04627