

Inspection Photos

10/31/2024

Operator: GUNNISON ENERGY LLC #10515

Location ID: 334446

Inspection Doc: 696206391

Gunnison County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 334446



October 31, 2024



October 31, 2024

Photo 1: Photos taken from the Location entrance, on the south east end of the Location. Photos provide an overview of the Location facing northwest and north. Photos show interim reclamation including, but not limited to, compaction alleviation, recontouring/regrading, replacement of soils/topsoil, and revegetation activities have not been performed pursuant to 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 334446



Photo 2: Photos 2-3 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north. Photos show interim reclamation including, but not limited to, compaction alleviation, recontouring/regrading, replacement of soils/topsoil, and revegetation activities have not been performed pursuant to 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 334446



October 31, 2024



October 31, 2024

Photo 3: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 334446



October 31, 2024



October 31, 2024

Photo 4: Photos 4-5 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photos show interim reclamation including, but not limited to, compaction alleviation, recontouring/regrading, replacement of soils/topsoil, and revegetation activities have not been performed pursuant to 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 334446



Photo 5: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources