

Inspection Photos

10/31/2024

Operator: GUNNISON ENERGY LLC #10515

Location ID: 427218

Inspection Doc: 696206393

Gunnison County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 427218



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location facing west, northwest, northeast to east. Photos show interim reclamation of areas not necessary for production has been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 427218



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 427218



Photo 3: Photos taken from the south end of the Location, facing northeast and south. Photos show interim reclamation has been performed. Photos right also shows sediment trap.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 427218



Photo 4: Photos taken from the north end of the Location, facing northwest and northeast. Photo shows interim reclamation has been performed. Photos also examples showing the stormwater diversion ditch along the perimeter of the pad.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 427218



Photo 5: Photo taken from the north end of the Location, facing north. Photo shows erosion degradation at the culvert outlet has been repaired.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 427218



Photo 6: Photos taken from the east end of the Location, facing southwest and northwest. Photos show interim reclamation has been performed. Photo right also shows sediment trap.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 427218

July 10, 2023



Photo 7: Photos taken from the tank battery facility on the west end of the Location. Photo left taken during the 7/10/2023 inspection; photo right taken during the 5/20/2024. Photos show hole within liner at the tank battery facility documented over multiple inspections.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 427218



Photo 8: Continued from photo 7. Photos show hole within liner at the tank battery facility has not been repaired; work to ensure that secondary containment remains impervious to contain a spill or release has not been performed, or has been insufficient.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources