

## Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25NENW

Location ID: 335105

Date: 10/28/2024



Oct 28, 2024 at 12:38:08 PM  
+39.499202,-108.170311 ±4.72m  
Parachute



Oct 28, 2024 at 12:55:00 PM  
+39.499258,-108.170573 ±4.72m  
Parachute

Photo # 8149 Entrance to location

Photo # 8174 Location

## Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25NENW

Location ID: 335105

Date: 10/28/2024



Oct 28, 2024 at 12:39:24 PM  
+39.498898,-108.171078 ±4.72m  
Parachute

Photo # 8150 Location



Oct 28, 2024 at 12:42:18 PM  
+39.499041,-108.170729 ±4.73m  
Parachute

Photo # 8155 Location



## Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25NENW

Location ID: 335105

Date: 10/28/2024



Photo # 8172 Location



Photo # 8179 NE corner of location

## Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25NENW

Location ID: 335105

Date: 10/28/2024



Photo # 8181 NW corner of location



Photo # 8182 SW corner of location



## Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25NENW

Location ID: 335105

Date: 10/28/2024



Oct 28, 2024 at 12:46:36 PM  
+39.499150,-108.170774 ±4.73m  
Parachute

Photo # 8158 Wildlife hazard



Oct 28, 2024 at 12:48:25 PM  
+39.499150,-108.170774 ±4.73m  
Parachute

Photo # 8159 Wildlife protection for methanol tank containment needs maintenance/netting is damaged/wildlife hazard



## Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25NENW

Location ID: 335105

Date: 10/28/2024



**Photo # 8163 Wildlife protection for methanol tank containment needs maintenance/netting is damaged/wildlife hazard**



**Photo # 8166 Wildlife protection for methanol tank containment needs maintenance/netting is damaged/wildlife hazard**



## Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25NENW

Location ID: 335105

Date: 10/28/2024



Photo # 8183 Debris



Photo # 8184 Debris



## Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25NENW

Location ID: 335105

Date: 10/28/2024



Photo # 8185 Debris



Photo # 8198 Debris



## Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25NENW

Location ID: 335105

Date: 10/28/2024



Photo # 8188 Unmarked deadman



Photo # 8189 Unmarked deadman



## Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25NENW

Location ID: 335105

Date: 10/28/2024



Photo # 8190 Unmarked deadman



Photo # 8193 Unmarked deadman