

# Final Reclamation and Stormwater Inspection

Date: 10/31/24

Operator: Noble Energy Inc - 100322

Location ID: 450477

Inspection Document #: 713901160

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

Location Name: Anderson Coombs 4 Tank

Battery

Location ID: 450477



**Photo 1.** The photo was taken at the Tank battery location facing East. The photo illustrates some perennial vegetative growth.

**Photo 2.** The photo was taken at the tank battery location facing Southeast. The photo illustrates debris on the location consisting of a mattress and piles of sod.

Inspection Photos

Location Name: Anderson Coombs 4 Tank

Battery

Location ID: 450477



**Photo 3.** The photo was taken at the tank battery location facing Northeast. The photo illustrates debris on location.



**Photo 4.** The photo was taken at the tank battery location facing West. The photo illustrates an overview of the location compared to reference areas as well as debris on location.