

# Final Reclamation and Stormwater Inspection

Date: 10/31/24

Operator: Noble Energy Inc - 100322

Location ID: 322565

Inspection Document #: 713901162

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

Location Name: ANDERSON-COOMBS #1

Location ID: 322565



**Photo 1.** The photo was taken at the tank battery location facing East. The photo illustrates some perennial vegetative growth dominated by areas of bare soil.

**Photo 2.** The photo was taken at the tank battery location facing West. Refer to the comment for photo 1.

Inspection Photos  
Location Name: ANDERSON-COOMBS #1  
Location ID: 322565



**Photo 3.** The photo was taken at the well location facing North. The photo illustrates the well location is part of a land use change to a dog park within residential.