

# Inspection Photos

October 28th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333811

Inspection Document #: 714001421

La Plata County, CO

Township: SWNW 34 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
 Location Name: Spanish Fork A1, A3  
 Location ID: 333811



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos  
Location Name: Spanish Fork A1, A3  
Location ID: 333811

10/28/24  
13° N



**Photo 2.** No weeds/weedy debris observed around the produced water tank.

Inspection Photos

Location Name: Spanish Fork A1, A3

Location ID: 333811



**Photo 3.** Musk Thistle observed along the western and northern edges of the disturbance.

Inspection Photos  
Location Name: Spanish Fork A1, A3  
Location ID: 333811



**Photo 4.** Active pasture reference area.