

Inspection Photos

October 3rd, 2024

Operator: Graham Royalty - 35047

Location ID: 392690

Inspection Document #: 714001422

Montezuma County, CO

Township: NESE 22 35N 20W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Veach Govt 1
Location ID: 392690



Photo 1. View of the project area taken from southern edge facing center using a drone.

Inspection Photos
Location Name: Veach Govt 1
Location ID: 392690



Photo 2. View of erosion channel forming on the eastern edge of the project area.