

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/27SWSE

Location ID: 335220

Date: 11/4/2024



Location Entrance – Photo #04672



Location – Photo #04673

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/27SWSE

Location ID: 335220

Date: 11/4/2024



Location – Photo #04676




Location – Photo #04675

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/27SWSE

Location ID: 335220

Date: 11/4/2024



Wildlife Entry Hazard – Photo #04677



Wildlife Entry Hazard – Photo #04678