

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ACCO TOSCO-66S95W/34SWNE

Location ID: 335219

Date: 11/4/2024



Location – Photo #04686




Location – Photo #04691

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ACCO TOSCO-66S95W/34SWNE

Location ID: 335219

Date: 11/4/2024



Nov 4, 2024 at 13:02:14
Parachute CO 81635
United States

Location – Photo #04689



Nov 4, 2024 at 13:02:01
Parachute CO 81635
United States

Location – Photo #04688



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ACCO TOSCO-66S95W/34SWNE

Location ID: 335219

Date: 11/4/2024



Wildlife Entry Hazard – Photo #04690



Rill Erosion in Access Road – Photo #04692

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ACCO TOSCO-66S95W/34SWNE

Location ID: 335219

Date: 11/4/2024



Rill Erosion in Access Road – Photo #04693



Rill Erosion in Access Road – Photo #04694